

From: [Coltrain, Katrina](#)
To: [Kady, Thomas](#)
Subject: Wilcox information
Date: Friday, February 26, 2016 11:52:00 AM
Attachments: [Property 002 - Sample Results.pdf](#)
[Property 006 - Sample Results.pdf](#)
[Property 008 - Sample Results.pdf](#)
[Property 011 - Sample Results.pdf](#)
[Wilcox_Summary_10-7-15 resident tabs.xlsx](#)
[DSCF0059.JPG](#)
[DSCF0060.JPG](#)
[DSCF0061.AVI](#)
[DSCF0062.AVI](#)
[DSCF0063.JPG](#)
[DSCF0064.JPG](#)
[DSCF0065.JPG](#)
[DSCF0066.JPG](#)
[DSCF0067.JPG](#)

Tom, please find the following attached to this email.

Property figures for grids where the geoprobe was pushed to depth to visually determine the presence of source material. No samples of this material were collected.

An excel summary file of the data results for the soils collected from the residential properties (0-24”).

Images of the cores pulled from Property 8(b) (6)/Tank 5.

Katrina Higgins-Coltrain
 Remedial Project Manager
 US EPA Region 6
 LA/OK/NM Section (6SF-RL)
 1445 Ross Avenue
 Dallas, Texas 75202
 214-665-8143







DSCF0061





DSCF0062











